



# Collaboration meeting CERN, 4./5. November 2004

Minutes at

<http://proj-hiptarget.web.cern.ch/>

→ Dates

→ collaboration meeting, minutes

# Access TT2A

- Current situation
  - No access to TT2A during running of PS
  - Impact on
    - modifications needed during run
    - Removal of setup
- **“Solution” 1**
  - Ask for dedicated PS MD without extraction
    - needs internal PS beam stoppers
  - Should be included in update to research board
  - Does not provide solution for maintenance
- **“Solution” 2**
  - Study possible beam losses in TT2
  - Modify beam line in TT2 to the needs
    - Additional “wall” next to dump
    - Moveable dump in nToF line

